

New Product Bulletin

An overheated clothes dryer could do this to your home.
Detect flammable lint buildup before it starts on fire
with...

NEW!

DrySafer™

Dryer Lint Alarm



Airflow Sensor

Alarm & Wall Mount



Installed on Dryer

Part # DS201401E Dealer: **\$39.99** Retail: **\$49.99**

Helps prevent fires • Immediate lint detection • Installs in minutes
Saves 77% energy • Dryer lasts longer • Fits all gas and electric dryers

If the airflow in the exhaust duct of your dryer becomes restricted due to excessive lint buildup, it could cause it to overheat and start on fire! Detect lint buildup and any other obstructions that could cause decreased airflow throughout your entire dryer's exhaust system with the DrySafer™ Dryer Lint Alarm.

The Airflow Sensor installs easily without requiring any tools, and connects directly to the wall mounted alarm. Immediately upon installation, the alarm begins to work and will sound if your dryer exhaust shows signs of dangerous levels of heat. This could be due to lint buildup as well as a thermostat malfunction or an overloaded dryer.

Prices subject to change 04/16/2015