



Dryer Bearing Repair Kit

Introducing a GE Dryer Repair Kit that works for all top load dryers made from 2002 - 2013



Drive Belt

Instructions

WE49X20697

Dealer \$20.10

List \$48.00

Kit includes:

1 WE12M29

1 WH00X5630

Bille Beit	Δ11. ψ12.50	Δ150 Φ50.25
Green Bearing Slide	Dlr. \$2.55	List \$5.50
White Bearing Slide	Dlr. \$3.99	List \$9.08
Top Bearing	Dlr. \$11.99	List \$31.08
Front Drum Felt	Dlr. \$6.12	List \$9.90
	Green Bearing Slide White Bearing Slide Top Bearing	Green Bearing Slide Dlr. \$2.55 White Bearing Slide Dlr. \$3.99 Top Bearing Dlr. \$11.99

Totals Dealer \$43.69 List \$100.39

Prices subject to change 04/25/2014

Dlr \$12.50 List \$30.25

N/C